

## Risk Assessment Summary Sheet

Ref 043

### Activity/Workplace; Vehicle Breakdown

Generic Risk Assessment						Risk Assessment after application of Control Measures					
Hazard	Risk	Risk Group	Likelihood	Severity	Risk Rating before controls	CONTROL MEASURES	Responsible Person	Likelihood	Severity	Risk Rating after controls	
Live traffic Poor visibility	Hit by other road users	Employees General Public	3	5	15			Provide reflective clothing and signage (if required) for use while working on the carriageway. Ensure that the breakdown vehicle is fitted with suitable warning lights which can be seen from a reasonable distance Ensure that employees engaged in this work are aware of the hazards involved and are competent in this work. Ensure that suitable and sufficient tools and equipment are provided to undertake this work safely. Make available assistance when the work involved requires additional help for manual handling purposes. When dealing with a breakdown on the carriageway use the breakdown vehicle as a barrier between the broken down vehicle and oncoming traffic Ensure that all tools and equipment carried in the breakdown vehicle are in good condition Use any manual handling aids and equipment provided for your safety Wear reflective clothing when working on the carriageway and cones/signage if required. Wear appropriate PPE while working away from the garage. Remember your limitations as a "lone worker" and request assistance when any task may have a higher degree of risk. Report any defects, concerns over safety matters to Line management. Wash hands/ face before eating, drinking or smoking. Do not adapt or use makeshift extensions with hand tools or power assisted tools. Relevant employees to receive Vehicle breakdown toolbox talks on an on going basis.	Line Management Employees	1	5
	Strains from handling portable equipment e.g. tyres		3	4	12	1	4			4	
	Slips trips and fall injuries		3	4	12	1	4			4	
	Injury/Infection from waste in the hopper or on tyres etc.		2	3	6	1	3			3	
	Injury from contact with hot engine/exhaust		3	3	9	1	3			3	
	Injury from slippage of hand/power tools		3	4	12	1	4			4	